



VOLKSWAGEN Sharan: 1HGK256			
Vinnnumber:	WVWZZZ7NZEV010629	Versionname:	SHARAN Highline BMT
First Registrationdate:	15/07/2014	Fiscalpower:	136PK
Expertise Mileage:	128985	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4213
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	225/50/17/98 V LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment	
Total cost ex VAT	3116,05
Door F R, Dent(s), PDR - Knock out without painting	63,00



Bumper R, Broken, Le - Replace and paint	766,80
--	--------



Rearlight L, Crack, E - Replace 132,00



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21



Door trim R L, Broken, E - Replace 64,00



Luggage space cover, Missing, E - Replace 288,00



Window R L door, Scratch(es), E - Replace 0,00



Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Ignition key, Missing, E - Replace 150,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------

