


PEUGEOT Expert: 1DG5787

Vinnnumber:	VF3XU9HM0CZ024165	Versionname:	EXPERT B/F MWB 229 L2H1 90PK
First Registrationdate:	11/05/2012	Fiscalpower:	
Expertise Mileage:	198779	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2304
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F:		Rear parking sensors:	
Type of headlighting:	Headlighting Halogen		
Type of GPS:	No GPS		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Power steering:	Yes
Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Wiper fluid level:	OK
Handbrake:	OK	Transmission:	OK
		Lighting:	OK
		Wiperblades:	OK

Degree of wear

	215/60/16/101 T Steel			
Summer tyres:	Fr.L.	Other: 4 mm	Fr.R.	Other: 4 mm
	Re.L.	Other: 5 mm	Re.R.	Other: 5 mm

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Total cost ex VAT:			556,52
Bumper R, Scratch(es), Acceptable:			0,00
<i>No pictures to display</i>			
Bonnet, Dent(s), Acceptable:			0,00
<i>No pictures to display</i>			
Bodywork, Not original part, Acceptable:			0,00
<i>No pictures to display</i>			
Ignition key, Missing, E - Replace:			150,00


Front bumper, Dent(s), Smart repair
110,64



Trunk door R R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	232,88
---	--------

No pictures to display