



CITROEN C5: 1FIV032			
Vinnumber:	<b>VF7RW9HL0DL506785</b>	Versionname:	<b>C5 TOURER Bus.GPS Plus</b>
First Registrationdate:	<b>10/07/2013</b>	Fiscalpower:	<b>113PK</b>
Expertise Mileage:	<b>142640</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Brown</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2704</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar <b>Tow bar removable</b>
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>225/60/15/95 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	<b>1421,35</b>
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>308,20</b>

Bumper R, Scratch(es), LI - Repair and paint (complete)		
<b>211,80</b>		

Front bumper, Scratch(es), LI - Repair and paint (complete)	
<b>211,80</b>	



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Tailgate, Dent(s), PDR - Knock out without painting	63,00
---	-------

