



VOLKSWAGEN Caddy: 1JEB220

Vinnnumber:	WV2ZZZ2KZFX058369	Versionname:	CADDY MAXI LIFE Trendl.102PK OMBOUW Dub.
First Registrationdate:	21/11/2014	Fiscalpower:	
Expertise Mileage:	189485	Power Kw:	75
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	NOT OK
Maintenance:	NOT OK		
Maintenance:	UITVOEREN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	NOT OK		
Registration Certificate Car (BE):	No		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 H Steel			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	728,93
-------------------	---------------

Tailgate handle, Scratch(es), Tu - Touch up	0,00
---	-------------



Rearview mirror glass R, Broken, E - Replace	13,50
--	--------------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing F R, Dent(s), PDR - Knock out without painting 63,00



Interior, Stain, Cleaning 75,00



Protection plate M, Hole, E - Replace 35,00



Wheel cover R L, Missing, E - Replace 22,50



Bumper R, Crack, Smart repair 110,64



Front bumper, Dent(s), Smart repair 110,64



Maintenance, Maintenance, Execute 0,00

No pictures to display

Wheel cover F R, Missing, E - Replace 22,50



Wheel cover R R, Missing, E - Replace 22,50



Wing R L, Scratch(es), LI - Repair and paint (complete)

231,15



Wheel cover F L, Missing, E - Replace

22,50

