



RENAULT Grand Kangoo: 1HFV111

| | | | |
|-----------------------------------|--------------------------|--------------|---------------------------|
| Vinnumber: | VF1KWB6H651004719 | Versionname: | GRAND KANGOO 109PK |
| First Registrationdate: | 10/07/2014 | Fiscalpower: | |
| Expertise Mileage: | 197377 | Power Kw: | 80 |
| Bodytype: | | Body color | Black |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Front | Rims summer | Steel |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 4219 |
| Number of doors | 5 | | |
| Number of seats | 7 | | |
| Number head rests | 7 | | |
| Rims summer | Steel | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | | |
|-------------------------|------------------------------|----------------------|--------------------------|
| Radio CD | | Luggage cover | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | Tow bar removable |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 195/65/15/91 T Steel | | | |
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 530,15 |
|-------------------|--------|

| | |
|-----------------------------------------------------|--------|
| Bumper R, Dent(s), LI - Repair and paint (complete) | 211,80 |
|-----------------------------------------------------|--------|



| | |
|---------------------------------------------------------|--------|
| Door R L, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---------------------------------------------------------|--------|





| | |
|------------------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wheel cover F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Trunk door R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |