



VOLVO XC60: 1ECL958			
Vinnumber:	YV1DZ8850D2399757	Versionname:	XC60 D4 Kinetic Geartr.163PK Aut.
First Registrationdate:	19/10/2012	Fiscalpower:	
Expertise Mileage:	122667	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4214
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS portable
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/65/17/104 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes

Total cost ex VAT	1159,08
Bumper corner R R, Scratch(es), It - Spot repair	115,56



Mirror side blinker R, Waterinfiltration, E - Replace	31,20
---	--------------



Wing R L, Dent(s), PDR - Knock out without painting 63,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker L, Waterinfiltration, E - Replace 31,20



Interior, Dirty, Acceptable 0,00



Front bumper, Dent(s), It - Spot repair 115,56



Door F L, Scratch(es), It - Spot repair 115,56



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16





Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Dent(s), PDR - Knock out without painting	63,00
---	-------



Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display