



FORD S-MAX: 1KDG745

| | | | |
|-----------------------------------|--------------------------|--------------|---|
| Vinnumber: | WF0SXXGBW5ER11249 | Versionname: | 1.6 TDCI 85KW S/S TITANIUM STYLE |
| First Registrationdate: | 7/04/2015 | Fiscalpower: | |
| Expertise Mileage: | 85758 | Power Kw: | 85 |
| Bodytype: | MPV | Body color | Light Grey |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 2607 |
| Number of doors | 5 | | |
| Number of seats | 7 | | |
| Number head rests | 7 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Radio CD | | Seats electric F L | |
| Windows electric F | | Seats electric F R | |
| Windows electric R | | Central consol F | |
| Cruise Control | | Front parking sensors | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Radio multimedia | | Type of Tow bar | Tow bar removable |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/50/17/98 V LightMetal | | | |
| Summer tyres: | Fr.L. | Goodyear: 7 mm | Fr.R. | Goodyear: 7 mm |
| | Re.L. | Goodyear: 6 mm | Re.R. | Goodyear: 6 mm |

Assistance equipment

| | | |
|---|------------|------------|
| | Compressor | Yes |
| Total cost ex VAT | | 288,00 |
| Luggage space cover, Missing, E - Replace | | 288,00 |

