



CITROEN C5: 1FKZ193

Vinnnumber:	VF7RW9HD8DL515467	Versionname:	C5 TOURER e-HDi Bus.GPS BMP 113PK Aut.
First Registrationdate:	1/08/2013	Fiscalpower:	
Expertise Mileage:	171720	Power Kw:	84
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	225/60/16/102 V LightMetal			
Summer tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	423,60
-------------------	--------

Door R R, Bad repair, P - Check	0,00
---------------------------------	------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bad repair, P - Check	0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	