



BMW SERIE 3: 1GN1530

Vinnumber:	WBA3D91010F406741	Versionname:	316d
First Registrationdate:	18/03/2014	Fiscalpower:	
Expertise Mileage:	57504	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2821
Maintenance:	IN 7000 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	HD
GPS storage	
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1360,88
-------------------	---------

Backrest cover F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Seat cover F L, Worn, P - Check	0,00
---------------------------------	------





Interior, Stain, Cleaning 50,00



Roof, Dent(s), PDR - Knock out without painting 82,80



Door panel F R, Hole, Smart repair 110,64



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 283,80



Wheel aperture R R, Scratch(es), It - Spot repair 115,56



Engine, Not functioning (well), P - Check 0,00



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door panel R R, Hole, Smart repair 110,64



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door panel F L, Hole, Smart repair 110,64



Sill trim L, Scratch(es), Acceptable 0,00

No pictures to display

Step L, Scratch(es), Acceptable 0,00

No pictures to display

no pictures to display