



<b>NISSAN Qashqai: 1FLF665</b>			
Vinnnumber:	<b>SJNJCAJ10U7187382</b>	Versionname:	<b>QASHQAI+2 2WD Tekna+Nis.Con.DPF 110PK</b>
First Registrationdate:	<b>5/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>145294</b>	Power Kw:	<b>81</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3422</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>215/60/17/96 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 2 mm</b>	Fr.R.	<b>Michelin: 2 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

<b>Assistance equipment</b>			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>639,02</b>
Maintenance book, Missing, E - Replace			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim R R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)			<b>220,18</b>



Bumper R, Scratch(es), Smart repair	<b>110,64</b>
-------------------------------------	---------------



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20

