



**RENAULT Clio: 1GHH821**

Vinnnumber:	<b>VF15R040H50269324</b>	Versionname:	<b>CLIO IV BER Expression</b>
First Registrationdate:	<b>7/02/2014</b>	Fiscalpower:	<b>75PK</b>
Expertise Mileage:	<b>62511</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1109</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/88 T Steel</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT 1185,60

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Bonnet, Dent(s), PDR - Knock out without painting 63,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Hole, Smart repair 64,32



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Broken, E - Replace 24,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 254,68



Steel rim F R, Deformed / Strained, Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Missing, E - Replace 24,00



Door F R, Scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover R L, Scratch(es), E - Replace 24,00






Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)	254,68
---	--------



Mirror side blinker R, Crack, E - Replace	28,80
---	-------

