



RENAULT Clio: 1ECK389			
Vinnnumber:	VF1KR2H4H47921450	Versionname:	CLIO BRE TomTom LIVE
First Registrationdate:	19/10/2012	Fiscalpower:	FAP 104g 89PK
Expertise Mileage:	75321	Power Kw:	65
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2622
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/60/15/84 H Steel			
Summer tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 7 mm

Assistance equipment	
Jack	Yes

Total cost ex VAT	1750,06
Wing F R, Scratch(es), Acceptable	0,00

<i>No pictures to display</i>	
Door F L, Dent(s), PDR - Knock out without painting	63,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,68
--	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	169,44
--	---------------



Bumper R, Dent(s) and scratch(es), Smart repair 110,64



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover F L, Scratch(es), E - Replace 24,00



Wheel cover R R, Scratch(es), E - Replace 24,00




Wheel cover F R, Scratch(es), E - Replace 24,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display