


VOLKSWAGEN Golf: 1HGV226

Vinnumber:	WVWZZZAUZFP513734	Versionname:	DIESEL
First Registrationdate:	17/07/2014	Fiscalpower:	
Expertise Mileage:	67560	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3620
Maintenance:	OVER 23.200 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	SD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting:	Headlighting Halogen	
Type of GPS:	GPS big screen color	
Type of Lining:	Lining leather	
Type of climate control:	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	672,55
-------------------	--------

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Rearview mirror housing R, Scratch(es), 67 - Polish	55,19
---	-------



Door F L, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Boot carpet, Dirty, Chemical cleaning 25,00



Bodywork, Not original part, Remove lettering 25,00



Luggage space cover, Damaged, E - Replace 240,00



Alloy rim F L, Scratch(es), Acceptable 0,00



Bonnet, Chemical pollution, 67 - Polish 0,00



Interior, Worn, Acceptable 0,00

