



PEUGEOT 308 SW : 1HFG400

Vinnnumber:	VF3LC9HPAES149646	Versionname:	
First Registrationdate:	7/07/2014	Fiscalpower:	
Expertise Mileage:	165883	Power Kw:	68
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2833
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Other: 5 mm	Fr.R.	Other: 5 mm
	Re.L.	Other: 6 mm	Re.R.	Other: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1155,24
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80





Wing R L, Dent(s), PDR - Knock out without painting 111,00



Dashboard, Hole, Smart repair 110,64




Seat cover F L, Hole, E - Replace 360,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door frame R L, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display