



AUDI A1: 1HJJ343

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnnumber: | WAUZZZ8X4EB139494 | Versionname: | A1 SB Attraction 5-tr.90PK Aut. |
| First Registrationdate: | 1/08/2014 | Fiscalpower: | |
| Expertise Mileage: | 63367 | Power Kw: | 66 |
| Bodytype: | Hatchback | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3532 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining leather |
| Type of climate control: | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 205/55/15/89 T LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
| | Re.L. | Continental: 6 mm | Re.R. | Continental: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|--------------------------|----------------|
| Total cost ex VAT | 2299,52 |
|--------------------------|----------------|

| | |
|--|---------------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 232,06 |
|--|---------------|



| | |
|--|---------------|
| Wing R R, Scratch(es), LI - Repair and paint (complete) | 246,56 |
|--|---------------|



Front bumper, Deformed / Strained, Le - Replace and paint

607,20



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display


Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

385,20



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

224,14



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

