



AUDI Q5: 1LNE079

Vinnumber:	WAUZZ8R7FA138008	Versionname:	
First Registrationdate:	27/10/2015	Fiscalpower:	
Expertise Mileage:	67482	Power Kw:	120
Bodytype:	SUV	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4528
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/17/108 W LightMetal				
Summer tyres:	Fr.L.	Toyo: 6 mm	Fr.R.	Toyo: 6 mm
	Re.L.	Toyo: 6 mm	Re.R.	Toyo: 6 mm

Assistance equipment

Total cost ex VAT	1253,97
Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16



Interior, Dirty, Chemical cleaning

150,00




Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 115,56



Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16





Rearlight L, Damaged, E - Replace

132,00

