



AUDI A5: 1FLU173			
Vinnnumber:	WAUZZZ8T8EA012427	Versionname:	A5 SB TDie S-line DPF 136PK
First Registrationdate:	9/08/2013	Fiscalpower:	
Expertise Mileage:	86777	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4716
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	245/40/18/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Firestone: 7 mm	Re.R.	Firestone: 7 mm

Assistance equipment	
Emergency spare wheel	Yes

Total cost ex VAT	1820,37
Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------





Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Xenon headlight L, Scratch(es), Acceptable 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), E - Replace 277,44



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 264,21



Tailgate, Bad repair, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

