


**AUDI A4: 1HFX259**

Vinnumber:	<b>WAUZZZ8K3FA013851</b>	Versionname:	<b>A4 AVANT TDie 136PK</b>
First Registrationdate:	<b>10/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>123931</b>	Power Kw:	<b>100</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>4118</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

GPS storage		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/16/99 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 3 mm</b>	Fr.R.	<b>Uniroyal: 3 mm</b>
	Re.L.	<b>Pirelli: 4 mm</b>	Re.R.	<b>Pirelli: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>3112,44</b>
Tailgate, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door R R, Scratch(es), LI - Repair and paint (complete)	<b>318,35</b>






Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 100,00



Sill outer R, Dent(s) and scratch(es), Le - Replace and paint 712,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 283,80





Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete) 259,80



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Rear window, Scratch(es), Acceptable 0,00

*No pictures to display*

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 340,18



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 366,35

