


BMW 3 BERLINE: 1JJN481

Vinnnumber:	WBA3E11010P588997	Versionname:	2.0 320D EFFICIENTDYN. (120KW) BERLINE
First Registrationdate:	5/01/2015	Fiscalpower:	
Expertise Mileage:	149798	Power Kw:	120
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3611
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	949,85
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), LI - Repair and paint (complete)	318,35



Roof, Scratch(es), LI - Repair and paint (complete)	481,50
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display


Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

No pictures to display

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Tailgate, Bad repair, Acceptable	0,00
----------------------------------	------



Wing F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display