



BMW 2: 1HLF955

Vinnumber:	WBA1H11010V233404	Versionname:	2 COUPE 220d 163PK
First Registrationdate:	19/08/2014	Fiscalpower:	
Expertise Mileage:	31688	Power Kw:	120
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3830
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2823,33
--------------------------	----------------

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
--	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	0,00
---	-------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 307,80



Door panel F R, Scratch(es), Smart repair 110,64



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s) and scratch(es), Le - Replace and paint 1231,51



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Sill outer R, Scratch(es), LI - Repair and paint (complete) 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80

