



BMW 3: 1GHH739			
Vinnnumber:	WBA3D91060F406623	Versionname:	3 BER 316d 116PK
First Registrationdate:	7/02/2014	Fiscalpower:	
Expertise Mileage:	119317	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3322
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/60/16/92 W LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			274,80
Wing F R, Scratch(es), Acceptable			0,00
No pictures to display			
Tailgate, Dent(s), Acceptable			0,00
No pictures to display			
Wing R L, Dent(s), PDR - Knock out without painting			63,00



Alloy rim F R, Scratch(es), Acceptable			0,00
No pictures to display			

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Door panel R R, Scratch(es), Acceptable	0,00
No pictures to display	
Roof, Hail damage, PDR - Hail	0,00
	