



BMW 3: 1GTH838

Vinnumber:	WBA3K11010F831934	Versionname:	3 TOURING 318d 143PK
First Registrationdate:	24/04/2014	Fiscalpower:	
Expertise Mileage:	183563	Power Kw:	105
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	1/01/2020	Parking lot:	2127
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Rear parking sensors	
Radio multimedia	Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	225/45/18/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment


Runflat **No**

Total cost ex VAT **2061,00**

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) **95,00**



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Broken, Le - Replace and paint 651,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (partial) 220,00



Seat cover F R, Stain, Cleaning 0,00

No pictures to display

Sill outer L, Scratch(es), LI - Repair and paint (partial) 220,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), E - Replace 370,00



Door R R, Scratch(es), LI - Repair and paint (partial) 220,00

