


BMW 320 D: 1FVA249

Vinnnumber:	WBA3E11060J709574	Versionname:	3 BER 320d Eff.Dynamics Ed.163PK
First Registrationdate:	4/11/2013	Fiscalpower:	
Expertise Mileage:	180929	Power Kw:	120
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2511
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	
GPS storage		
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 W LightMetal				
Summer tyres:	Fr.L.	Kleber: 3 mm	Fr.R.	Kleber: 3 mm
	Re.L.	Kleber: 2 mm	Re.R.	Kleber: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			235,80
Alloy rim F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Roof pillar L, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete)			235,80



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	