



**BMW 4 GRAN COUPE: CM7577**

Vinnumber:	<b>WBA4E91020G288064</b>	Versionname:	<b>2.0 420D (140KW) GRAN COUPE</b>
First Registrationdate:	<b>28/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>64501</b>	Power Kw:	<b>140</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3504</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/40/19/89 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 4,5 mm</b>	Fr.R.	<b>Bridgestone: 4,5 mm</b>
	Re.L.	<b>Bridgestone: 4,5 mm</b>	Re.R.	<b>Bridgestone: 4,5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>57,00</b>
-------------------	--------------

Backrest cover F L, Scratch(es), Acceptable	<b>0,00</b>
---	-------------



Protection plate M, Hole, E - Replace	<b>57,00</b>
---------------------------------------	--------------



Bumper R, Repaired, Acceptable

0,00

*No pictures to display*