



BMW 5 TOURING: 1LBD568

Vinnumber:	WBA5L51070G088963	Versionname:	2.0 520D (140KW) XDRIVE AUTO TOURING
First Registrationdate:	7/08/2015	Fiscalpower:	
Expertise Mileage:	138640	Power Kw:	140
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2108
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Sun Roof electric
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Seats F heated	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting: Headlighting Halogen	
Type of GPS: GPS big screen color	
Type of Lining: Lining leather	
Type of climate control: Autom climate control	
Head-up Display	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/98 Y LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Total cost ex VAT	625,32
Bumper R, Scratch(es), LI - Repair and paint (complete)	308,16



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bonnet, Dent(s), PDR - Knock out without painting

63,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

254,16

