



| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| BMW X4: GL1610 | | | |
| Vinnumber: | WBAXX110700R40338 | Versionname: | 2.0 XDRIVE20D (140KW) |
| First Registrationdate: | 9/12/2015 | Fiscalpower: | 4WD |
| Expertise Mileage: | 199518 | Power Kw: | 140 |
| Bodytype: | SUV | Body color: | Dark Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | 4 Weel | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3826 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| | |
|--------------------------------|------------------------------|
| Options | |
| Radio CD | Sun Roof electric |
| Windows electric F | Central consol F |
| Windows electric R | Luggage cover |
| Cruise Control | Front parking sensors |
| Steering wheel multifunctional | Rear parking sensors |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Xenon |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining leather |
| Type of climate control: | Autom climate control |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| Degree of wear | | | | |
| | 225/60/17/99 H LightMetal | | | |
| Winter tyres: | Fr.L. | Continental: 3 mm | Fr.R. | Continental: 3 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

| | |
|---|------|
| Assistance equipment | |
| Total cost ex VAT | 0,00 |
| Door R L, Chemical polution, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Stone chip(s), Acceptable | 0,00 |

No pictures to display