



BMW 5: 1EFI482

Vinnumber:	WBAXB51050DX77042	Versionname:	5 TOURING 530dA Start/Stop 258PK aut
First Registrationdate:	15/11/2012	Fiscalpower:	
Expertise Mileage:	128271	Power Kw:	190
Bodytype:	Break	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2631
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 V LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment






















Runflat	Yes
---------	------------

Total cost ex VAT 1260,92

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16

		
		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
		
Tailgate, Scratch(es), Acceptable		0,00
No pictures to display		
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)		254,16
		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Sill outer R, Crack, LI - Repair and paint (complete)		372,60
