


MERCEDES A: 1LBH222

Vinnnumber:	WDD1760121V093116	Versionname:	1.5 A 180 CDI
First Registrationdate:	10/08/2015	Fiscalpower:	
Expertise Mileage:	51818	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4724
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 V Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			301,80
Bonnet, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R R, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Wheel cover R L, Scratch(es), E - Replace			30,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F L, Scratch(es), Acceptable 0,00



Wheel cover F R, Scratch(es), E - Replace 30,00

