



| FORD Focus: 682BVV | | | |
|-------------------------|--------------------------|--------------|---|
| Vinnumber: | WF0SXXGCD5AM30952 | Versionname: | FOCUS CLIP Econetic II DPF 109PK |
| First Registrationdate: | 13/07/2010 | Fiscalpower: | |
| Expertise Mileage: | 66200 | Power Kw: | 80 |
| Bodytype: | Break | Body color: | Silver |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1211 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| Options | |
|--------------------------|-------------------------------|
| Radio CD | Luggage cover |
| Windows electric F | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Manual climate control |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | |
|----------------|----------------------------------|-------|----------------|
| Summer tyres: | 195/65/15/91 H LightMetal | | |
| | Fr.L. | Fr.R. | Michelin: 4 mm |
| | Re.L. | Re.R. | Michelin: 5 mm |

| Assistance equipment | |
|----------------------|------------|
| Repair kit | Yes |
| Compressor | Yes |

| | |
|---|--------|
| Total cost ex VAT | 308,20 |
| Roof, Chemical polution, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wheel cover R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |



| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |