



OPEL INSIGNIA SPORTS TOURER: 1KHR949

Vinnumber:	WOLGM8ES0F1054718	Versionname:	2.0 CDTI ECOFLEX 103KW S/S EDITION
First Registrationdate:	6/05/2015	Fiscalpower:	
Expertise Mileage:	188625	Power Kw:	103
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3431
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats F L ventilated	
Windows electric F		Seats F R ventilated	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia			
Type of headlighting:	Headlighting Xenon		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	520,00
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Tailgate, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Bad repair, Acceptable	0,00
--------------------------------	------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Chemical pollution, Acceptable	0,00
--	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display