



MERCEDES E BERLINE: 1LGU895

Vinnumber:	WDD2120061B254189	Versionname:	2.1 E 200 BLUETEC ELEGANCE EDITION E
First Registrationdate:	24/09/2015	Fiscalpower:	
Expertise Mileage:	160221	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3209
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Front parking sensors	
Steering wheel multifunctional	Rear parking sensors	
Seats F heated	Type of Tow bar	No Tow bar
Radio multimedia		
Type of headlighting:	Headlighting LED	
Type of GPS:	GPS big screen color	
Type of Lining:	Lining leather	
Type of climate control:	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/17/95 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 2680,51

Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Roof pillar L, Dent(s) and scratch(es), LI - Repair and paint (complete) 264,22



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 382,02



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 264,21



Door F R, Scratch(es), LI - Repair and paint (complete) 382,02



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02

