


PEUGEOT 208: 1EMW238

Vinnnumber:	VF3CC8HR0CT124013	Versionname:	208 BER Active 68PK
First Registrationdate:	25/01/2013	Fiscalpower:	
Expertise Mileage:	112224	Power Kw:	50
Bodytype:	Hatchback	Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3110
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Windows electric F		Luggage cover	
Cruise Control		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	506,32
-------------------	--------

Bumper grille, Broken, E - Replace	109,00
------------------------------------	--------



Wheel cover F R, Broken, E - Replace	24,00
--------------------------------------	-------







Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
	
Interior, Dirty, Acceptable	0,00
No pictures to display	
Seat cover F L, Hole, Smart repair	64,32
	
Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover R R, Broken, E - Replace	24,00
	
Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Door F L, Bad repair, Paint	0,00
	
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
