


MINI Mini: 1HLU725

Vinnnumber:	WMWXN110X03A01109	Versionname:	MINI BER One 95PK
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	85623	Power Kw:	70
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3411
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/55/16/87 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment


Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1668,82
-------------------	---------

Front bumper, Scratch(es), Smart repair	110,64
---	--------



Door F R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Registration Document, Missing, E - Replace 150,00

No pictures to display


Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Ignition key, Missing, E - Replace 150,00

No pictures to display

Roof, Dent(s) and scratch(es), LI - Repair and paint (complete) 481,50



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

