


OPEL Insignia: 1HHL041

Vinnumber:	W0LGM8ER7E1155363	Versionname:	INSIGNIA BRE ecoFL.Business 120PK
First Registrationdate:	24/07/2014	Fiscalpower:	
Expertise Mileage:	160141	Power Kw:	88
Bodytype:		Body color:	Green
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2706
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Seats electric F L
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	758,28
-------------------	--------

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------



Alloy rim F R, Rust, LI - Repair and paint (complete)	95,00
---	-------



Tailgate, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Alloy rim R R, Rust, LI - Repair and paint (complete) 95,00



Alloy rim F L, Rust, LI - Repair and paint (complete) 95,00



Windscreen, Stone chip(s), Windscreen repair 88,20



Door R L, Dent(s), Acceptable 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Alloy rim R L, Rust, LI - Repair and paint (complete) 95,00

