



OPEL Zafira: 1GKS887			
Vinnumber:	WOLPE9E36E2061404	Versionname:	ZAFIRA TOURER ecoFL.Cosmo S/S 136PK
First Registrationdate:	5/03/2014	Fiscalpower:	
Expertise Mileage:	102622	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2403
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	Headlighting Xenon	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/60/16/95 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			518,76
Door F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00



Door R L, Scratch(es), Acceptable			0,00
-----------------------------------	--	--	-------------

Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
<i>No pictures to display</i>	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20

