



RENAULT Clio: 1GDH674			
Vinnnumber:	VF17R040H50139714	Versionname:	CLIO IV BRE Business
First Registrationdate:	7/01/2014	Fiscalpower:	75PK
Expertise Mileage:	207012	Power Kw:	55
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3404
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			96,00
Wheel cover R R, Scratch(es), E - Replace			24,00



Wheel cover F L, Broken, E - Replace			24,00
---	--	--	--------------



Wheel cover F R, Broken, E - Replace 24,00



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Repaired, Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 24,00



Bonnet, Chemical polution, Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00



Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display