



OPEL Corsa: 1GIB788

Vinnumber:	W0L0SDL68E4106455	Versionname:	CORSA BER ecoFL.Enjoy St/St DPF 95PK
First Registrationdate:	13/02/2014	Fiscalpower:	
Expertise Mileage:	144236	Power Kw:	70
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3832
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-leather
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	453,06
-------------------	--------

Roof, Repaired, Acceptable	0,00
----------------------------	------

No pictures to display

Wing R R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Door R R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display