



**OPEL Insignia: 1HHK346**

Vinnumber:	<b>WOLGM8ER0E1146374</b>	Versionname:	<b>INSIGNIA BRE ecoFL.Business 120PK</b>
First Registrationdate:	<b>24/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>74503</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2602</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/60/16/95 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>415,36</b>
-------------------	---------------

Rearview mirror housing L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------



Ceiling, Stain, Cleaning	<b>25,00</b>
--------------------------	--------------



Wing R R, Dent(s), PDR - Knock out without painting 63,00



Alloy rim F L polished, Rust, Acceptable 0,00



Front bumper, Scratch(es), It - Spot repair 115,56



Tailgate, Scratch(es), Acceptable 0,00



Alloy rim F R polished, Rust, Acceptable 0,00



Bumper F L, Scratch(es), Acceptable 0,00



Seat cover R L, Deformed / Strained, P - Check 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Step R, Scratch(es), Acceptable 0,00

