


VOLKSWAGEN Golf: 1HLS171

Vinnumber:	WVWZZZAUZFP007243	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	21/08/2014	Fiscalpower:	
Expertise Mileage:	97326	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1127
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1068,70
-------------------	---------

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Door R R, Bad repair, Acceptable	0,00
----------------------------------	------



Door F R, Bad repair, Acceptable	0,00
----------------------------------	------



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Wing R L, Bad repair, Acceptable 0,00



Boot carpet, Damaged, E - Replace 100,00



Windscreen, Scratch(es), E - Replace 487,20

