



**TOYOTA AURIS: 1PDD420**

|                                    |                          |              |                              |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber:                        | <b>SB1MS3JE80E250715</b> | Versionname: | <b>1.8 HYBRID LOUNGE CVT</b> |
| First Registrationdate:            | <b>8/06/2016</b>         | Fiscalpower: | <b>AUTO</b>                  |
| Expertise Mileage:                 | <b>38043</b>             | Power Kw:    | <b>73</b>                    |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                  |
| Gearbox:                           | <b>Automatic</b>         | Body color:  | <b>GRIS</b>                  |
| Transmission:                      | <b>Front</b>             | Paint type:  | <b>Metalic</b>               |
| Fueltype:                          | <b>Hybrid Petrol</b>     | Rims summer: | <b>Aluminium</b>             |
| Battery functioning:               | <b>Yes</b>               | Oil level:   | <b>OK</b>                    |
| Number of doors:                   | <b>5</b>                 |              |                              |
| Number of seats:                   | <b>5</b>                 |              |                              |
| Number head rests:                 | <b>4</b>                 |              |                              |
| Rims summer:                       | <b>Aluminium</b>         |              |                              |
| Category:                          | <b>Passenger Car</b>     |              |                              |
| Oil level:                         | <b>OK</b>                |              |                              |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                              |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| Radio CD                       |                              | Central consol F      |
| GPS storage                    |                              | Luggage cover         |
| GPS storage                    | <b>HD</b>                    | Front parking sensors |
| Windows electric F             |                              | Rear parking sensors  |
| Windows electric R             |                              |                       |
| Cruise Control                 |                              |                       |
| Steering wheel multifunctional |                              |                       |
| Seats F heated                 |                              |                       |
| Radio multimedia               |                              |                       |
| Type of headlighting           | <b>Headlighting LED</b>      |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                     |       |                     |
|---------------|----------------------------------|---------------------|-------|---------------------|
|               | <b>225/45/17/91 W LightMetal</b> |                     |       |                     |
| Summer tyres: | Fr.L.                            | <b>Dunlop: 3 mm</b> | Fr.R. | <b>Dunlop: 3 mm</b> |
|               | Re.L.                            | <b>Dunlop: 5 mm</b> | Re.R. | <b>Dunlop: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>322,00</b> |
|-------------------|---------------|

|                                   |             |
|-----------------------------------|-------------|
| Door F L, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

*No pictures to display*

|  |              |
|--|--------------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--|--------------|





|   |        |
|---|--------|
| Rocker panel inner F R, Scratch(es), Acceptable | 0,00   |
| <i>No pictures to display</i>                   |        |
| Tyre F L, Tear, E - Replace                     | 132,00 |



|  |       |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|   |      |
|---|------|
| Bumper R, Dent(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>                 |      |
| Bonnet, Stone chip(s), Acceptable             | 0,00 |
| <i>No pictures to display</i>                 |      |
| Rocker panel inner R R, Dent(s), Acceptable   | 0,00 |
| <i>No pictures to display</i>                 |      |
| Interior, Dirty, Acceptable                   | 0,00 |
| <i>No pictures to display</i>                 |      |
| Door R L, Scratch(es), Acceptable             | 0,00 |
| <i>No pictures to display</i>                 |      |
| Windscreen, Stone chip(s), Acceptable         | 0,00 |
| <i>No pictures to display</i>                 |      |