



<b>SEAT Altea XL: 1GNP949</b>			
Vinnnumber:	<b>VSSZZZ5PZER015049</b>	Versionname:	<b>ALTEA XL I-Tech 140PK</b>
First Registrationdate:	<b>19/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>150627</b>	Power Kw:	<b>103</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3704</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		







<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

<b>Assistance equipment</b>			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>882,24</b>
<b>Front bumper, Scratch(es), LI - Repair and paint (complete)</b>			<b>211,80</b>



<b>Roof pillar L, Dent(s), Acceptable</b>	<b>0,00</b>
---	-------------

<i>No pictures to display</i>		
Bonnet, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Roof pillar R, Dent(s), PDR - Knock out without painting		63,00
		
Trunk lid covering R, Scratch(es), Smart repair		110,64
		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
		
Door F L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		