



**TOYOTA Yaris: 1GRS899**

Vinnnumber:	<b>VNKKD3D370A098982</b>	Versionname:	<b>YARIS BER Hybrid Comfort</b>
First Registrationdate:	<b>10/04/2014</b>	Fiscalpower:	<b>74PK Aut.</b>
Expertise Mileage:	<b>78123</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3701</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>172/65/15/84 H Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 3 mm</b>	Fr.R.	<b>Bridgestone: 3 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
-----------------------	------------

<b>Total cost ex VAT</b>	<b>739,46</b>
--------------------------	---------------

<b>Interior, Dirty, Cleaning</b>	<b>50,00</b>
----------------------------------	--------------



Door F L, Scratch(es), LI - Repair and paint (complete)

254,68



Tailgate, Dent(s), LI - Repair and paint (complete) 241,34



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 24,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44

