



TOYOTA Auris: 1EWN028

Vinnumber:	SB1MS3JE60E006254	Versionname:	AURIS BER HSD Hybr.Comfort CVT 99PK Aut.
First Registrationdate:	8/04/2013	Fiscalpower:	
Expertise Mileage:	37107	Power Kw:	73
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2731
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	No
------------	------------	------------	-----------

Total cost ex VAT	1540,61
-------------------	----------------


Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Tyre repair kit, Missing, E - Replace 210,53



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bonnet, Dent(s), LI - Repair and paint (complete) 290,08



Roof, Dent(s), Acceptable 0,00

No pictures to display