



VOLVO S80: 1FLQ272

Vinnnumber:	YV1AS31A1E1177636	Versionname:	S80 BER D3 Kinetic 136PK
First Registrationdate:	8/08/2013	Fiscalpower:	
Expertise Mileage:	156402	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2806
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/16/95 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment


Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	567,66
-------------------	---------------

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bonnet, Bad repair, Acceptable	0,00
--------------------------------	-------------



Tailgate, Scratch(es), LI - Repair and paint (complete)	362,02
---	---------------



Front bumper, Deformed / Strained, Smart repair 110,64



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

