



VOLVO XC60: 1FDU796

Vinnumber:	YV1DZ31A1E2502719	Versionname:	XC60 D3 Kinetic Start/Stop 136PK
First Registrationdate:	3/06/2013	Fiscalpower:	
Expertise Mileage:	86723	Power Kw:	100
Bodytype:	SUV	Body color	Light Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2330
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/104 V LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	882,53
-------------------	---------------

Rearview mirror housing L, Missing, Le - Replace and paint	110,00
--	---------------




Wing F L, Scratch(es), LI - Repair and paint (complete)	264,21
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------




Bonnet, Bad repair, Acceptable 0,00



Wing R R, Bad repair, Acceptable 0,00



Bonnet, Hail damage, PDR - Hail 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16





Door R L, Scratch(es), Acceptable

0,00

No pictures to display