



## VOLVO XC60: 1EWW883

Vinnnumber:	<b>YV1DZ31A1D2456461</b>	Versionname:	<b>XC60 D3 Kinetic Start/Stop 136PK</b>
First Registrationdate:	<b>10/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>147989</b>	Power Kw:	<b>100</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2322</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunction	Type of Tow bar	<b>Tow bar removable</b>
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

235/65/17/104 W LightMetal				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>

## Assistance equipment

Total cost ex VAT	566,66
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F R, Deformed / Strained, Smart repair	110,64



Protection plate M, Tear, E - Replace

74,00



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*