



**RENAULT KADJAR: CX7453**

Vinnnumber:	<b>VF1RFE00056182532</b>	Versionname:	<b>1.5 Energy dCi 110 EDC Bose? Edition</b>
First Registrationdate:	<b>19/09/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>92289</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2426</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Windows electric F		Seats electric F L	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunction		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	<b>Headlighting LED</b>	Type of Tow bar	<b>No Tow bar</b>
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/19/96 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>95,00</b>
Alloy rim F L polished, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Windscreen, Stone chip(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>





Tailgate, Dent(s), Acceptable

0,00

*No pictures to display*