


SKODA Octavia: 1GPQ387

Vinnnumber:	TMBJG7NE9E0186416	Versionname:	OCTAVIA COMBI
First Registrationdate:	26/03/2014	Fiscalpower:	GreenLine Ambition 110PK
Expertise Mileage:	144284	Power Kw:	81
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2314
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	420,80
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Bumper R, Scratch(es), Acceptable

0,00

Protection plate M, Deformed / Strained, E - Replace	74,00
--	-------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Roof, Dent(s), PDR - Knock out without painting	102,60
---	--------



Bumper grille, Crack, E - Replace	32,40
-----------------------------------	-------

