



TOYOTA Auris: 1HJH320

Vinnnumber:	SB1ZS3JE90E097171	Versionname:	AURIS TOUR.SP.HSD
First Registrationdate:	1/08/2014	Fiscalpower:	Dynamic CVT 99PK Aut.
Expertise Mileage:	166517	Power Kw:	73
Bodytype:	Break	Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3723
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Total cost ex VAT	724,24
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Boot carpet, Worn, Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00

