





VOLKSWAGEN Caddy: 1HUP168			
Vinnnumber:	WV2ZZZ2KZFX043198	Versionname:	CADDY MAXI LIFE 2PLC Comfortl. BM 102PK
First Registrationdate:	7/10/2014	Fiscalpower:	
Expertise Mileage:	125406	Power Kw:	75
Bodytype:		Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3205
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	205/55/16/94 H Steel			
	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			820,67
Trunk door R L, Scratch(es), It - Spot repair			115,56

		Door R R, Scratch(es), LI - Repair and paint (complete)	238,76
---	---	---	--------

		Wing R L, Scratch(es), Acceptable	0,00
---	---	-----------------------------------	------

No pictures to display

Rear window, Scratch(es), E - Replace 307,50



Bumper R, Scratch(es), LI - Repair and paint (complete) 158,85



Wing F R, Dent(s), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display